

# Uncoated Carbide Grade Machining Recommendations for Milling

Type of Material	Hardness		Maximum Surface Speeds (ft/min)								
	Rc	BHN	G-60 G-53	G-70	G-50	G-10 G-02	G-23	G-20M	G-01M	G-40	G-74
<b>Non-Alloy Carbon Steel:</b>											
<i>C &lt; 0.25 %</i>		110	720	780	460	N/A	N/A	N/A	N/A	N/A	N/A
<i>C &lt; 0.80 %</i>	6	150	550	600	350	N/A	N/A	N/A	N/A	N/A	N/A
<i>C &lt; 1.40 %</i>	33	310	440	480	280	N/A	N/A	N/A	N/A	N/A	N/A
<b>Low-Alloy Steels:</b>											
<i>Annealed, Medium - High Carbon</i>	12	180	460	500	290	N/A	N/A	N/A	N/A	N/A	N/A
<i>Hardened</i>	36	330	300	320	190	N/A	N/A	N/A	N/A	N/A	N/A
<b>High-Alloy Steels:</b>											
<i>Annealed</i>	16	200	280	300	180	N/A	N/A	N/A	N/A	N/A	N/A
<i>Hardened</i>	41	380	200	220	130	N/A	N/A	N/A	N/A	N/A	N/A
<b>High-Alloy Tool Steel:</b>											
<i>Hardened</i>	36	330	290	310	180	N/A	N/A	N/A	N/A	N/A	N/A
<b>Cast Steel:</b>											
<i>Non-Alloy</i>	6	150	550	600	350	N/A	N/A	N/A	N/A	N/A	N/A
<i>Low-Alloy</i>	16	200	440	480	280	N/A	N/A	N/A	N/A	N/A	N/A
<i>High-Alloy</i>	16	200	390	420	250	N/A	N/A	N/A	N/A	N/A	N/A
<b>Stainless Steels:</b>											
<i>Ferritic, 400 Series</i>	16	200	440	480	280	N/A	N/A	N/A	N/A	N/A	N/A
<i>Austenitic, 300 Series</i>	16	200	N/A	N/A	N/A	310	400	350	N/A	N/A	N/A
<b>Gray, Pearlitic Cast Irons:</b>											
<i>Low Tensile</i>	12	180	N/A	N/A	N/A	450	600	500	N/A	N/A	N/A
<i>High Tensile</i>	26	260	N/A	N/A	N/A	200	250	230	N/A	N/A	N/A
<b>Nodular / Malleable Irons:</b>											
<i>Short Chipping</i>	6	150	680	740	440	N/A	N/A	N/A	N/A	N/A	N/A
<i>Long Chipping</i>	21	230	400	440	250	N/A	N/A	N/A	N/A	N/A	N/A
<b>Aluminum Alloys:</b>			N/A	N/A	N/A	1400	1800	1500	N/A	N/A	N/A
<b>Brass, Copper, Bronze:</b>			N/A	N/A	N/A	500	600	550	N/A	N/A	N/A
<b>Hardened Steels (&gt; 50 Rc):</b>			N/A	50	N/A	N/A	N/A	N/A	N/A	N/A	N/A
<b>Chilled, Hardened Irons (&gt; 50 Rc):</b>			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
<b>Titanium, Refractory Metals:</b>			N/A	N/A	N/A	100	150	130	N/A	N/A	N/A
<b>Nickel &amp; Iron Based Superalloys:</b>											
<i>Inconels</i>			N/A	N/A	N/A	80	N/A	100	N/A	N/A	N/A
<i>Hastelloys</i>			N/A	N/A	N/A	120	N/A	140	N/A	N/A	N/A
<i>Waspoloys</i>			N/A	N/A	N/A	80	N/A	100	N/A	N/A	N/A
<i>Renes</i>			N/A	N/A	N/A	60	N/A	80	N/A	N/A	N/A
<i>Monels</i>			N/A	N/A	N/A	60	N/A	80	N/A	N/A	N/A
<b>Cobalt Based Superalloys:</b>											
<i>Stellites</i>			N/A	N/A	N/A	50	N/A	60	N/A	N/A	N/A
<i>Haynes Alloys</i>			N/A	N/A	N/A	50	N/A	60	N/A	N/A	N/A

Feeds should be in the range of 0.003 in/tooth to 0.012 in/tooth.  
 Higher speeds require lower feeds, whereas, low speeds use higher feed rates.  
 A good general starting point for feed rate in milling is 0.004 in/tooth.